



INNOVATIVE
AUTOSPORTS

Innovative Autosports LLC
2323 Tarpley Road
Unit A116
Carrollton, TX 75006
(972) 418-1996
Info@innovativeautosports.com
https://innovativeautosports.com/

Invoice for RO #7938

Service Advisor: Tory Ramsey
Posted Date: 12/15/23 at 04:16 PM CST
Vehicle: 2019 Porsche 911 Carrera GTS

	<p>2019 Porsche 911 Carrera GTS 3.0L 6Cyl GAS DCJA Turbocharged VIN: WP0AB2A92KS114807 License: N/A Color: N/A Odometer In: 13962 / Out: 13962</p>	<p>RO # 7938 Time-In: 10/11/23 at 08:12 AM CDT Save Parts: No</p>
--	--	---

Client concerns:

- Recently purchased vehicle. Check over vehicle.
- Check Centerlock Function
- Install a trickle charger
- Diagnose and repair driver's door noise

1 - Pre-Purchase Inspection (Standard)		
Labor:	Pre-Purchase Inspection (Standard)	\$370.00
✓ Approved on 10/11/23 at 08:13 AM CDT		\$370.00

2 - Oil Service		
Labor:	Perform Oil Change & Fluid Top Off	\$75.00
Parts:	Oil Filter Kit	1 \$35.36 \$35.36
	Oil	8.5 \$10.93 \$92.91
	Oil Drain Plug - Plastic	1 \$9.74 \$9.74
✓ Approved on 11/14/23 at 05:00 PM CST		Subtotal \$213.01 + est. Tax \$11.39 \$224.40

3 - Remove & Replace Spark Plugs		
Labor:	Remove & Replace Spark Plugs	\$425.50
Part:	Spark plug	6 \$28.75 \$172.50
Discount:	Preferred Customer Discount	-\$17.25
✓ Approved on 11/14/23 at 05:00 PM CST		Subtotal \$580.75 + est. Tax \$12.81 \$593.56

4 - Remove & Replace Suspension Control Arm		
Labor:	Remove & Replace Front Lower Suspension Control Arms, Extended Tie Rod Ends, and Thrust Arms (Both Sides)	\$1,221.00
Parts:	Lower Control Arm Kit (each)-Cup Series	2 \$794.50 \$1,589.00
	Extended Toe Links	2 \$280.00 \$560.00
	Spacer, GT3 Lower Control Arm Conversion	4 \$12.00 \$48.00
	Litronic Bracket	2 \$35.00 \$70.00
	Tension Link/ Thrust Arm	2 \$360.00 \$720.00
	Hook Plate Shim .250	2 \$9.64 \$19.28
	Hook Plate Shim .040	2 \$13.16 \$26.32
	Hook Plate Shim .190	4 \$13.37 \$53.48
Fee:	Shipping from Tarett	\$34.38
Discount:	Preferred Customer Discount	-\$308.61
✓ Approved on 10/19/23 at 08:38 PM CDT		Subtotal \$4,032.85 + est. Tax \$229.14 \$4,261.99

5 - Remove & Replace Brake Pads				
<i>Labor:</i>	Remove & Replace Front Brake Pads			\$185.00
	Remove & Replace Rear Brake Pads			\$185.00
<i>Parts:</i>	Front Brake Pad Set	1	\$572.63	\$572.63
	Rear Brake Pad Set	1	\$625.84	\$625.84
<i>Fee:</i>	Shipping			\$20.44
<i>Discount:</i>	Preferred Customer Discount			-\$119.85
✓ Approved on 10/19/23 at 08:38 PM CDT			<i>Subtotal \$1,469.06 + est. Tax \$88.99</i>	\$1,558.05

6 - Brake Flush (Motul RBF 600)				
<i>Labor:</i>	Brake fluid flush			\$93.00
<i>Part:</i>	RBF 600 Dot 4 Racing Brake Fluid	2	\$20.49	\$40.98
✓ Approved on 11/14/23 at 05:00 PM CST			<i>Subtotal \$133.98 + est. Tax \$3.38</i>	\$137.36

7 - Add Center Radiator and Grill Mesh				
<i>Labor:</i>	Add Center Radiator and Grill Mesh			\$1,295.00
<i>Parts:</i>	Radiator	1	\$700.78	\$700.78
	Air guide	1	\$65.00	\$65.00
	Sealing frame	1	\$46.55	\$46.55
	Rubber bush	2	\$12.45	\$24.90
	Rubber bush	2	\$11.85	\$23.70
	Coolant hose	1	\$54.15	\$54.15
	Coolant hose	1	\$71.08	\$71.08
	Hexagon nut	4	\$3.38	\$13.52
	Cover	1	\$20.15	\$20.15
	Cover	1	\$20.15	\$20.15
	Seal	1	\$12.21	\$12.21
	Seal	2	\$5.90	\$11.80
	Air guide Matt black	1	\$289.76	\$289.76
	Antifreeze / Coolant (Gallon container)	2	\$43.51	\$87.02
	Coolant additive	1	\$14.50	\$14.50
	Hexagon XXL Grill Mesh Sheet	2	\$125.00	\$250.00
	Retaining Frame Black	1	\$179.63	\$179.63
<i>Discount:</i>	Preferred Customer Discount			-\$188.49
✓ Approved on 11/14/23 at 05:00 PM CST			<i>Subtotal \$2,991.41 + est. Tax \$139.95</i>	\$3,131.36

8 - Mount and Balance 4 Tires				
<i>Labor:</i>	Mount and Balance 4 Tires			\$125.00
<i>Parts:</i>	POTENZA SPORT - 245/35/20	2	\$343.99	\$687.98
	POTENZA SPORT - 305/30/20	2	\$502.99	\$1,005.98
<i>Fee:</i>	Used Tire Disposal			\$16.00
✓ Approved on 10/17/23 at 06:25 AM CDT			<i>Subtotal \$1,834.96 + est. Tax \$139.75</i>	\$1,974.71

9 - Alignment				
<i>Labor:</i>	Alignment			\$199.00
✓ Approved on 10/17/23 at 06:25 AM CDT				\$199.00

10 - Remove rattle to identify rattle and repair.				
Note: Driver door panel rattling during test drive.				
<i>Labor:</i>	Remove door panel			\$92.50
✓ Approved on 11/17/23 at 08:09 AM CST				\$92.50

11 - Replace engine air filter				
Labor:	Remove rear bumper and replace engine air filter.			\$185.00
Part:	BMC High Flow Air Filter	1	\$339.90	\$339.90
Fee:	Shipping			\$15.23
Discount:	Preferred Customer Discount			-\$33.99
✓ Approved on 11/17/23 at 08:09 AM CST			Subtotal \$506.14 + est. Tax \$25.24	\$531.38

12 - Phone Mount with charger				
Part:	Phone mount with wireless charging	1	\$135.00	\$135.00
✓ Approved on 11/21/23 at 09:07 AM CST			Subtotal \$135.00 + est. Tax \$11.14	\$146.14

13 - Add Battery Tender				
Labor:				\$92.50
Part:	Battery Charger 7002	1	\$168.29	\$168.29
Discount:	Preferred Customer Discount			-\$16.83
✓ Approved on 11/21/23 at 09:07 AM CST			Subtotal \$243.96 + est. Tax \$12.50	\$256.46

14 - Replace key battery				
✓ Approved on 11/21/23 at 03:16 PM CST			0	0

RO Fees				
Fee:	Shop Supplies			\$20.00
			Subtotal	\$20.00

Payment by credit card will incur a 3.0% surcharge to the total invoice. Payment by cash or check will not incur a surcharge

Thank you for your business. The work is complete and your payment is due upon pickup of the vehicle. Mechanics liens may be placed on vehicles until repairs are paid for in full. Please contact us promptly if you have any questions about anything we did.

This warranty is restricted to certain types of auto repairs. Repairs must be performed with parts determined to be of appropriate quality and must accompany best practices for that repair. "Wear and tear" and maintenance items** are not covered by 24 month / 24,000 mile warranty. All repairs MUST be completed at Innovative Autosports. Warranties are not transferable. Innovative Autosports will not pay another facility to perform warranty repairs. To keep warranties in effect, some maintenance items may apply. Innovative Autosports reserves the right to void any warranty if there is evidence of abuse, modification, neglect, intentional damage or repair of another system has affected the original warranted repair. Innovative Autosports will not warranty any parts of the vehicle that was not repaired at Innovative Autosports originally, regardless of how damaged. Other exceptions may apply.

Deposits are non-refundable. No returns or refunds on special ordered items or electrical parts. There is no warranty for used parts or customer supplied parts.

Total Repair Order & Signature:

Total Jobs:	\$13,401.59
Total Fees:	\$106.05
Discounts:	-\$685.02
Subtotal:	\$12,822.62
Taxes:	\$674.28
Grand Total:	\$13,496.90
BALANCE DUE:	\$0.00

X _____

✓ PAID

Completed Transactions				
██████	██████	██████	██████	██████



INNOVATIVE
AUTOSPORTS

Innovative Autosports LLC
2323 Tarpley Road
Unit A116
Carrollton, TX 75006
(972) 418-1996
Info@innovativeautosports.com
https://innovativeautosports.com/

Invoice for RO #9056

Service Advisor: Tory Ramsey

Posted Date: 09/27/24 at 09:58 AM CDT

Vehicle: 2019 Porsche 911 Carrera GTS

	<p>2019 Porsche 911 Carrera GTS 3.0L 6Cyl GAS DCJA Turbocharged VIN: WP0AB2A92KS114807 License: N/A Color: N/A Odometer In: 16898 / Out: 16913</p>	<p>RO # 9056 Time-In: 09/11/24 at 08:57 AM CDT Save Parts: No</p>
--	--	---

Client concerns:

- Oil Service
- Noise in rear end (Passenger rear)

1 - Innovative Autosports Service Inspection		
Labor:	Innovative Autosports Standard Inspection	\$0.00
✓ Approved on 09/11/24 at 08:58 AM CDT		0 0

2 - Oil Service		
Labor:	Perform Oil Change & Fluid Top Off	\$75.00
Parts:	Oil Filter Kit	1 \$35.36 \$35.36
	Oil	8.5 \$10.93 \$92.91
	Oil Drain Plug - Plastic	1 \$9.74 \$9.74
✓ Approved on 09/11/24 at 08:58 AM CDT		Subtotal \$213.01 + est. Tax \$11.39 \$224.40

3 - Credit Card Surcharge		
Sublet:	Payment by credit card will incur a 3.0% surcharge to the total invoice, Payment by cash or check will not incur a surcharge (\$235.05)	\$7.05
✓ Authorized on 09/27/24 at 07:44 AM CDT		\$7.05

RO Fees		
Fee:	Shop Supplies	\$10.65
		Subtotal \$10.65

Payment by credit card will incur a 3.0% surcharge to the total invoice. Payment by cash or check will not incur a surcharge

Thank you for your business. The work is complete and your payment is due upon pickup of the vehicle. Mechanics liens may be placed on vehicles until repairs are paid for in full. Please contact us promptly if you have any questions about anything we did.

This warranty is restricted to certain types of auto repairs. Repairs must be performed with parts determined to be of appropriate quality and must accompany best practices for that repair. "Wear and tear" and maintenance items** are not covered by 24 month / 24,000 mile warranty. All repairs MUST be completed at Innovative Autosports. Warranties are not transferable. Innovative Autosports will not pay another facility to perform warranty repairs. To keep warranties in effect, some maintenance items may apply. Innovative Autosports reserves the right to void any warranty if there is evidence of abuse, modification, neglect, intentional damage or repair of another system has affected the original warranted repair. Innovative Autosports will not warranty any parts of the vehicle that was not repaired at Innovative Autosports originally, regardless of how damaged. Other exceptions may apply.

Deposits are non-refundable. No returns or refunds on special ordered items or electrical parts. There is no warranty for used parts or customer supplied parts.

Total Repair Order & Signature:

Total Jobs: \$220.06
Total Fees: \$10.65
Subtotal: \$230.71
Taxes: \$11.39
Grand Total: \$242.10
BALANCE DUE: \$0.00

X

PAID

Completed Transactions					
[REDACTED]	[REDACTED]	[REDACTED]	[REDACTED]	[REDACTED]	[REDACTED]



INNOVATIVE
AUTOSPORTS

Innovative Autosports LLC
2323 Tarpley Road
Unit A116
Carrollton, TX 75006
(972) 418-1996
Info@innovativeautosports.com
https://innovativeautosports.com/

Invoice for RO #9743

Service Advisor: Tory Ramsey

Posted Date: 03/24/25 at 01:53 PM CDT

Vehicle: 2019 Porsche 911 Carrera GTS

	<p>2019 Porsche 911 Carrera GTS 3.0L 6Cyl GAS DCJA Turbocharged VIN: WP0AB2A92KS114807 License: N/A Color: N/A Odometer In: 17372 / Out: 17372</p>	<p>RO # 9743 Time-In: 03/24/25 at 08:48 AM CDT Save Parts: No</p>
--	--	---

Client concerns:

- Oil Service

1 - Innovative Autosports Service Inspection		
Labor:	Innovative Autosports Standard Inspection	\$0.00
✓ Approved on 03/24/25 at 08:49 AM CDT		0 0

2 - Oil Service			
Labor:	Perform Oil Change & Fluid Top Off		\$75.00
Parts:	Oil Filter Kit	1	\$35.36 \$35.36
	Oil	8.5	\$10.93 \$92.91
	Oil Drain Plug - Plastic	1	\$9.74 \$9.74
✓ Approved on 03/24/25 at 08:49 AM CDT		Subtotal \$213.01 + est. Tax \$11.39	\$224.40

RO Fees		
Fee:	Shop Supplies	\$10.65
		Subtotal \$10.65

RO Discounts		
Discount:	PCA Member Discount	-\$13.80
		Subtotal -\$13.80

Payment by credit card will incur a 3.0% surcharge to the total invoice. Payment by cash or check will not incur a surcharge

Thank you for your business. The work is complete and your payment is due upon pickup of the vehicle. Mechanics liens may be placed on vehicles until repairs are paid for in full. Please contact us promptly if you have any questions about anything we did.

This warranty is restricted to certain types of auto repairs. Repairs must be performed with parts determined to be of appropriate quality and must accompany best practices for that repair. "Wear and tear" and maintenance items** are not covered by 24 month / 24,000 mile warranty. All repairs MUST be completed at Innovative Autosports. Warranties are not transferable. Innovative Autosports will not pay another facility to perform warranty repairs. To keep warranties in effect, some maintenance items may apply. Innovative Autosports reserves the right to void any warranty if there is evidence of abuse, modification, neglect, intentional damage or repair of another system has affected the original warranted repair. Innovative Autosports will not warranty any parts of the vehicle that was not repaired at Innovative Autosports originally, regardless of how damaged. Other exceptions may apply.

Deposits are non-refundable. No returns or refunds on special ordered items or electrical parts. There is no warranty for used parts or customer supplied parts.

Total Repair Order & Signature:

Total Jobs: \$213.01
Total Fees: \$10.65
Discounts: -\$13.80
Subtotal: \$209.86
Taxes: \$10.25
Grand Total: \$220.11
BALANCE DUE: \$0.00

X

PAID

Completed Transactions					
[REDACTED]	[REDACTED]	[REDACTED]	[REDACTED]	[REDACTED]	[REDACTED]